

MCB 212/205 BICARB TANK REPLACEMENT

This tech note explains what is required should damage occur to either the Mix Tank or to the Distribution Tank on the MCB 212 or 205 Dual Tank Bicarb Mix and Delivery Unit.

If damage has occurred to the 100-gallon Mix or to the 100-gallon Distribution Tank on the MCB 212 or 205 models making either one unusable, a replacement kit designed specifically for each one of those tanks is available as a complete set.

Each kit includes one (1) tank and stand (welded together) along with all of the necessary fittings and holes (except for the tank lid) for proper realignment and reconnection. A new set of labels are included for valve identification, tank level, and tank identification. These will need to be applied once the new tank is installed. The kit also includes an instruction sheet; p/n 3030090 for the Mix Tank and p/n 3030091 for the Distribution Tank, detailing how-to replace the damaged tank. These kits do not include a tank cover. If a new replacement cover is required, use p/n 3027015.

Use the following chart to identify which kit is required for the Dual Tank Bicarb Mix and Delivery Unit, Model MCB 212 or 205.

MCB 212/205 Tank	Tank Size	Replacement Bicarb Tank Kit Part Number
Mix Tank	100-Gallon	3030088
Distribution Tank	100-Gallon	3030089

Please be sure to contact Technical Support at 800-633-3080 if you have any questions or require further assistance.